



This is the Biltmore home of the Vanderbilt family which is located outside Asheville, North Carolina. The structure is made from stone blocks and it has several basement layers. It took over 6 years to build this massive structure.



There are a lot of carvings in the stone. Note how the mold and grime is on the tops and bottoms of the carvings.





A close up of the stone carvings and statues show how much craftsmanship went into their creation. Note the color of the metal rain downspouts. The mold and grime is on the undersides of the stone carvings.



The metal sheeting, which is most likely thick brass, turns two different colors.





The metal used for the window framing has no iron in it which is why it is not showing signs of any rust. My guess is that it is also solid brass or a mixture of metal alloys with brass in it. Note the green color on the face of the brass sheeting have several different shades and is not consistent in color.



The brass sheeting caps on the roof peeks get a lot of sun which helps keep the green color the same shade. The color is a light green-lime flat shade.